









































Move on to the 2nd screw. Fix it into the hole and spin to the next hole for the 3rd screw. Same goes to the 4th one











